



CNC Tool List

Measurement Tools

- 0"–6" or 0"–8" Digital Caliper
- Outside Micrometer Set (0"–1", 1"–2", 2"–3")
- Inside Micrometer Set (2"–8")
- Depth Micrometer Set (0"–4")
- Dial Indicator (1") with Magnetic Base
- Test Indicator (.030 travel, .0005 grad)
- Small Hole Gauge Set
- Telescoping Gauge Set
- Machinist Scales: 6" (16R x2) and 12" (black)

Layout & Setup Tools

- Combo Square Set (4-piece)
- Precision Square Set (2"–6", 4-piece)
- 1-2-3 Block Set
- Parallels, 1/8" thick, 10-piece set
- V-Block Set
- Machinist Jack Set
- Edge Finder Set
- Granite Surface Plate (9" × 12")

Hand Tools

- Allen Wrench Set
- Torx Driver Set
- Wrench Set (Open/Box End)
- Socket Set (1/4" drive)
- Socket Set (3/8" drive)
- Dead Blow Hammers (10 oz, 21 oz)
- Pick Set
- Insert Screwdriver Bits