

ELT (Entry Level Tools)

10" or 12" Crescent Wrench	Leather Jacket (covering arms & chest to apron)
12" Lineman Pliers	Lock for Locker
16' Tape Measure	Metal Gauge
4" Sander/Grinder	Rod Pouches (optional)
8" Pliers or Vise Grips	Safety Glasses
Carbide Tipped Scriber	Scientific Calculator
Center Punch	Striker or Spark Lighter & Tip Cleaners (standard set)
Chipping Hammer	Welding & Cutting Goggles with Lens Shade #4 or #5
Combination Square	Welding Gloves
Ear Plugs	Welding Helmet & Lens Shade #10,#11 or #12
Fillet weld gauge set	Wire Brush
Leather Apron (covering waist to ankles)	Wrap Around
Leather High Top Boots	